



DLAŽBA

VZORY POKLÁDEK


ASTI kombi



| | |
|----------------------------------|--|
| 120/83,5/7 | = 2 ks 30/16,7/7 + 2 ks 50/16,7/7 + 4 ks 40/12,5/7 + 2 ks 40/16,7/7 + 4 ks 30/12,5/7 + 4 ks 50/12,5/7 |
| Spotřeba ks/m² | 1 vrstva (kombiforma) = 1,03 m ² |



| | |
|----------------------------------|--|
| Vzor 1 | Prodej na vrstvy: 1 vrstva (kombiforma) = 2 ks 30/16,7/7 + 2 ks 50/16,7/7 + 4 ks 40/12,5/7 + 2 ks 40/16,7/7 + 4 ks 30/12,5/7 + 4 ks 50/12,5/7 |
| Spotřeba ks/m² | 1 vrstva (kombiforma) = 1,03 m ² |




| | |
|----------------------------------|--|
| Vzor 2 | Prodej na vrstvy: 1 vrstva (kombiforma) = 2 ks 30/16,7/7 + 2 ks 50/16,7/7 + 4 ks 40/12,5/7 + 2 ks 40/16,7/7 + 4 ks 30/12,5/7 + 4 ks 50/12,5/7 |
| Spotřeba ks/m² | 1 vrstva (kombiforma) = 1,03 m ² |


DLAŽBA

VZORY POKLÁDEK

ASTI kombi



| | |
|--------|--|
| Vzor 3 | Prodej na vrstvy: 1 vrstva (kombiforma) |
| | = 2 ks 30/16,7/7 + 2 ks 50/16,7/7 + 4 ks 40/12,5/7 + 2 ks 40/16,7/7 + 4 ks 30/12,5/7 + 4 ks 50/12,5/7 |
| | Spotřeba ks/m ² 1 vrstva (kombiforma) = 1,03 m ² |



| | |
|--------|--|
| Vzor 4 | Prodej na vrstvy: 1 vrstva (kombiforma) |
| | = 2 ks 30/16,7/7 + 2 ks 50/16,7/7 + 4 ks 40/12,5/7 + 2 ks 40/16,7/7 + 4 ks 30/12,5/7 + 4 ks 50/12,5/7 |
| | Spotřeba ks/m ² 1 vrstva (kombiforma) = 1,03 m ² |